

Warnvermerk / Warning notice	DIN ISO 10889-1:2006-01
Datum / Date	2023-03-17
Werkzeughalter mit Zylinderschaft — Teil 1: Zylinderschaft, Aufnahmebohrung; Technische Lieferbedingungen (ISO 10889-1:2004) Tool holders with cylindrical shank - Part 1: Cylindrical shank, location bore; Technical delivery conditions (ISO 10889-1:2004) Porte-outil à queue cylindrique - Partie 1: Queue cylindrique, alésage de réception; Conditions techniques de livraison (ISO 10889-1:2004) In DIN ISO 10889-1:2006-01 sind folgende Korrekturen auszuführen: In Tabelle 2 muss für d_1 die Toleranzangabe von h6 durch H6 ersetzt werden. In DIN ISO 10889-1:2006-01 the following changes shall be made: In Table 2, for d_1, the tolerance specification of h6 must be replaced by H6. HINWEIS: Wir weisen darauf hin, dass der vorliegende Fehler negative Auswirkungen haben kann. Es liegt in der Verantwortung des Anwenders, den Sachverhalt bei der Anwendung der Norm angemessen zu berücksichtigen, um einen etwaigen Schaden zu vermeiden. Bitte prüfen Sie unverzüglich, ob und inwieweit in Ihrem Fall eine Schadengefahr besteht und reagieren Sie entsprechend. Falls Sie das Dokument selbst nicht anwenden, jedoch den/die betroffenen Anwender kennen, leiten Sie diesen Warnvermerk unverzüglich an den/die Anwender weiter. INFORMATION: Please note that this error can have negative implications. When applying the standard, it is the user's responsibility to take due account of this warning notice in order to avert potential damage. Please check without delay whether, and to what extent, there is a risk of damage in your case, and take the necessary action. If you do not apply the document yourself but are aware of any users who may be affected, please forward this warning notice on to them without delay.	

- Leerseite -