

DIN ISO 29661:2016-11 (E)

Reference radiation fields for radiation protection - Definitions and fundamental concepts (ISO 29661:2012)

Contents	Page
National foreword	4
National Annex NA (informative) Referenced documents and corresponding European and international documents	4
National Annex NB (informative) Bibliography	5
Introduction	6
1 Scope	6
2 Normative references	7
3 Terms and definitions	7
3.1 General	7
3.2 Quantities and conversion coefficients	17
4 Symbols	25
5 Application of the measurement quantities and units	28
5.1 Measurement quantities for area monitoring	28
5.2 Measurement quantities for individual monitoring	28
5.3 Establishing of the measurement quantities for area and individual monitoring	28
6 Calibration and determination of the response in reference radiation fields	29
6.1 General principles	29
6.1.1 Parts to be irradiated	29
6.1.2 Conditions of the dosimeter under test	29
6.1.3 Point of test and reference point	30
6.1.4 Axes of rotation	30
6.1.5 Reference conditions and standard test conditions for influence quantities	30
6.2 Calibration in reference radiation fields	30
6.2.1 Concept of calibration	30
6.2.2 Determination of the conventional quantity value from a secondary or a working standard	31
6.2.3 Determination of the corrected indicated value and the calibration coefficient	31
6.2.4 Determination of the measured value	32
6.3 Determination of the response in reference radiation fields	33
6.4 Methods for the determination of the calibration coefficient	33
6.4.1 Procedures	33
6.4.2 Sequential irradiation of standard and dosimeter	34
6.4.3 Simultaneous irradiation of standard and dosimeter	34
6.4.4 Calibration and determination of the response using a calibrated monitor device	36
6.4.5 Calibration and determination of the response using a reference radionuclide source unit	37
6.5 Special considerations for area dosimeters (area survey meters)	37
6.5.1 Reference point and reference direction	37
6.5.2 Irradiation conditions	38

6.6	Special considerations for personal dosimeters	38
6.6.1	General	38
6.6.2	Phantoms	39
6.6.3	Reference direction and reference point	39
6.6.4	Irradiation conditions	40
6.6.5	Simultaneous irradiation of several dosimeters	41
7	Uncertainty	42
8	Certificates	42
Annex A (normative)	List of reference conditions and standard test conditions	43
Annex B (normative)	Description of the calibration coefficient	44
	Bibliography	46

Bilder

Figure 1	— Reference direction and direction of radiation incidence of personal dosimeter mounted on water slab phantom [see 6.6.2 a)]	15
Figure 2	— Sketch of simultaneous irradiation of standard and dosimeter	35
Figure 3	— Positioning of whole-body dosimeter at slab phantom surface (reference direction normal to phantom surface)	41

Tabellen

Table 1	— Symbols	25
Table A.1	— Reference conditions and standard test conditions	43